

Line Length Measurement

Comments

Glider Service B23378LM Job Number Wing Model GIN - YETI 6 / 23 Hours Serial number BN02-Q1100070P Colours White, Burgundy Blue Technician / Date James / 31-10-2024 Summary Excellent V. Good Good Fair Tired Failed Overall glider condition The glider is in an very good condition with very little signs of use. As the glider has been flown at the coast, the wing has a Comments salty feel to it. It may be worth getting the wing out on a dewy morning to see if the salt can easily be removed. There are no signs that the salt has had a negative impact on the serviceability of the wing. **Porosity** Excellent V. Good Good Fair Tired Failed Left Center Riaht 275+ 275+ 275+ Top Surface **Bottom Surface** 275+ Comments Technician: James Fabric Strength Result: Pass 🗸 Comments Technician: James Riser Inspection Excellent V. Good Good Failed Damaged Comments Webbing Brake handles & keepers Maillons Maillons inserts / O rings Pulleys or rings Speed system / trimmers Comments Technician: James Canopy Inspection Excellent V. Good Good Fair Tired Failed Damaged Comments Leading edge Cell walls Top surface Bottom surface ~ Trailing edge Stitching Line tabs Colour fading **~** Delamination Cleanliness Some small sand deposits. Comments Some small sand deposits removed. Technician: James No. Line Inspection Excellent Very Good Good Fair Tired Failed replaced Comments 0 Main lines Mid and uppers **~** 0 Brake lines 0 Comments Technician: James Line Strength Assessment Line type Failed Line code Damaged V. Good Good Fair Tired Comments Comments Line condition and little flying hours preclude the need for testing Technician: James

Full measure of all overall line lengths by laser completed. See separate page for full details

Technician: James