Brakes

	Very Good	Good	Fair	Acceptable	Poor			Ν	lotes:				
Line condition	Х												
Symmetry						FTS							
Knot Adequacy		Х											
Brake Handle	Х												
Brake Fixing	Х												
Line Length	А	ctu	ıal		F	TS	Line Plan		Reset?	Yes	No	Х	
Line length Tip st.	Α	ctu	ıal				Line Plan		Reset?	Yes	No		

Risers

	Very Good	Good	Fair	Acceptable	Poor	Notes:
Webbing	Х					
Stitching Fading	Х					
Fading	Х					
Pulleys	Х					
Maillons	Х					
Line Tidies	Х					
Speed system line	х					

٠.	hc	
١I	มว	

	Very Good	Good	Accepta	Poor	Notes:
	<u>o</u>		ole		
Condition	Х				
Damage Notes					

Please make sure pre-flight checks and a test inflation are carried out before flying.

Thank you,



Old Chapel Church Hill Newhaven BN9 9LN 01273 516332

Paraglider Service Report

Customer Details

Name L Greenway

Paraglider Details

Manufacturer Ozone

Model Roadster 3

Size 30

Weight Range 110-140 (195)

Serial No V32A014 (Oct 20)

Colour(s) Red Blue White

Porosity

Top Surface at Leading Edge

Left				Centre	>	200	Right		
Very Good	х	Good	į	Fair	į	Accep	otable	Poor	į

Service Notes

General Glider Condition

Very Good	Good	Fair	Acceptable	Poor
Х				

Checked By: Ross

Date: 23/05/2024

	Tape Repairs	Panel Replacements	Notes:	Material A Lines	Acceptable Fair Good Very Good	Poor	Notes	:
Previous Repairs				B Lines	X X			
New Repairs				C Lines	x			
Stitching		<u> </u>	Good	D Lines	x			
Stitering			3000	Upper Brake Lines	x			
Material	Fair Good Very Good	Poor Acceptable	Notes:	Line Strength Main Centre A/B	Act	ual	Minimum	Acceptable? Yes No
Fading	х			Wall Certic Ay B				Yes No
Delamination	x	 						Yes No
Line Tabs	x	 		 				Yes No
Cleanliness	x	 		<u> </u>				163 110
Cloth condition	X	 		1				
Ciotil collation	^			Replaced Lines	1 10	eft		Right
Top Surface				Replaced Lilles	Upper	Main	Upper	Main
Top surface				A Lines	Оррег	IVIGITI	Оррег	IVIGIII
	Tape Repairs	Panel Replacements	Notes:	B Lines C Lines D Lines Brake Lines		1		
Previous Repairs								
New Repairs				<u></u>				
Stitching			Good	Line Symmetry	Chec			ceptable?
					Yes	No	Yes	No
	<	≥		Notes:		F	TS	
Material	Fair Good Very Good	Poor	Notes:	Line Measurement de	one? (FTS,NTT)	Yes	x No	
Fading	х			Notes:				
Delamination	x							
Cleanliness	x			1				
Cloth condition	x			-				

Lines

Under Surface