Brakes

	Very Good	Good	Fair	Acceptable	Poor	Notes:							
Line condition	Х												
Symmetry						FTS, S	ee report						
Knot Adequacy	Х												
Brake Handle	Х												
Brake Fixing	Х												
Line Length	Α	ctu	ıal		F	ΓS	Line Plan		Reset?	Yes	Х	No	
Line length Tip st.	Α	ctu	ıal				Line Plan		Reset?	Yes		No	

Risers

	Very Good	Good	Fair	Acceptable	Poor	Notes:
Webbing	х					
Stitching	Х					
Fading	Х					
Pulleys	Х					
Maillons	Х					
Line Tidies	Х					
Speed system line	х					

Ribs

	Very Good	Good	air	Acceptable	Poor	Notes:
Condition	Х					
Damage Notes						

Please make sure pre-flight checks and a test inflation are carried out before flying.

Thank you,



Old Chapel Church Hill Newhaven BN9 9LN 01273 516332

Paraglider Service Report

Customer Details

Name Andy Fenton

Paraglider Details

Manufacturer Phi

Model Tenor 2

Size 21

Weight Range 75 - 105 KG

Serial No 010297J

Colour(s) Blue Red Orange

Porosity

Top Surface at Leading Edge

Left	į			Centre	>	200	Right	i !	
Very Good	х	Good	i	Fair	į	Accep	otable	Poor	į

Service Notes

General Glider Condition

Very Good	Good	Fair	Acceptable	Poor
х				

Checked By: Liam

Date: 10/06/2024

	pe Repairs	Panel placements	Notes:		Material	y Good	good	Fair	eptable	Poor			Note	s:		
	•	V			ines	х										
Previous Repairs					ines	Х										
New Repairs					ines	Х										
Stitching			Good		ines	Х										
		 		Up	per Brake Lines	Х										
Material	Fair Good Very Good	Poor Acceptable	Notes:		e Strength in Centre A/B				Act	ual	<u> </u>	Mini	imum	Acc Yes	ceptab N	
Fading	х			N/A										Yes	N	
Delamination	х													Yes	N	0
Line Tabs	х													Yes	N	
Cleanliness	х										JI.					
Cloth condition	х															
				Rei	olaced Lines				Le	ft				Right	t	
Top Surface							Jpp	er			Main		Upper		Mai	n
	Tape Repairs	Panel Replacements	Notes:	B L C L D I	ines ines ines ines ke Lines											
Previous Repairs																
New Repairs																
Stitching		•	Good	Lin	e Symmetry			Cl	hec	ked?			Ad	ceptal	ole?	
						\	'es	ŀ			No	1	Yes		No	
	Ver	Acc		No	tes:							FTS				
Material	Fair Good Very Good	Poor ceptable	Notes:	Lin	e Measurement do	ne? (l	TS,	NTT)		Ye	es	x No			
Fading	х			No	tes:											
Delamination	х															
Cleanliness	х															
Cloth condition	x															
	. , .															

Lines

Under Surface