



Old Chapel  
Church Hill  
Newhaven  
BN9 9LN  
01273 516332

### Paraglider Service Report

#### Brakes

	Very Good	Good	Fair	Acceptable	Poor	Notes:				
Line condition		x	x							
Symmetry		x								
Knot Adequacy		x								
Brake Handle		x								
Brake Fixing		x								
Line Length	Actual			Prev FTS	Line Plan		Reset?	Yes	No	x
Line length Tip st.	Actual				Line Plan		Reset?	Yes	No	

#### Risers

	Very Good	Good	Fair	Acceptable	Poor	Notes:				
Webbing		x								
Stitching	x	x								
Fading		x								
Pulleys	x	x								
Maillons	x	x								
Line Tidies	x	x								
Speed system line		x	x							

#### Ribs

	Very Good	Good	Fair	Acceptable	Poor	Notes:				
Condition		x								
Damage Notes										

Please make sure pre-flight checks and a test inflation are carried out before flying.

Thank you,

#### Customer Details

Name David Williams

#### Paraglider Details

Manufacturer Air Design

Model Rise 4

Size S

Weight Range 72-92

Serial No XB3253P211222P (May 21)

Colour(s) Red Orange White

#### Porosity

Top Surface at Leading Edge

Left	61	Centre	162	Right	85
------	----	--------	-----	-------	----

Very Good	Good	x	Fair	Acceptable	Poor
-----------	------	---	------	------------	------

#### Service Notes

General Glider Condition

Very Good	Good	Fair	Acceptable	Poor
	x			

Checked By: Ross

Date: 04/09/2024

**Under Surface**

	Tape Repairs	Panel Replacements	Notes:
Previous Repairs			
New Repairs			
Stitching			Good

<b>Material</b>	Very Good	Good	Fair	Acceptable	Poor	Notes:
Fading		x				
Delamination		x				
Line Tabs		x				
Cleanliness		x				
Cloth condition		x				

**Top Surface**

	Tape Repairs	Panel Replacements	Notes:
Previous Repairs			
New Repairs			
Stitching			Good

<b>Material</b>	Very Good	Good	Fair	Acceptable	Poor	Notes:
Fading		x				
Delamination		x				
Cleanliness		x				
Cloth condition		x				

**Lines**

<b>Material</b>	Very Good	Good	Fair	Acceptable	Poor	Notes:
A Lines		x				
B Lines		x				
C Lines		x				
D Lines		x				
Upper Brake Lines		x				

<b>Line Strength</b>	Actual	Minimum	Acceptable?	
Main Centre A/B			Yes	No
			Yes	No
			Yes	No
			Yes	No

<b>Replaced Lines</b>	Left		Right	
	Upper	Main	Upper	Main
A Lines				
B Lines				
C Lines				
D Lines				
Brake Lines				

<b>Line Symmetry</b>	Checked?		Acceptable?	
	Yes	x	No	
Notes:			Yes	x
			No	

Line Measurement done? (FTS,NTT)  Yes  No  x

<b>Notes:</b>