



Old Chapel
Church Hill
Newhaven
BN9 9LN
01273 516332

Paraglider Service Report

Brakes

	Very Good	Good	Fair	Acceptable	Poor	Notes:
Line condition		x	x			
Symmetry		x				
Knot Adequacy		x				
Brake Handle		x				
Brake Fixing		x				Oiled.
Line Length	Actual	122/1225	Line Plan	122	Reset?	Yes x No
Line length Tip st.	Actual		Line Plan		Reset?	Yes No

Risers

	Very Good	Good	Fair	Acceptable	Poor	Notes:
Webbing	x	x				
Stitching	x					
Fading	x	x				
Pulleys	x					
Maillons	x					
Line Tidies		x				
Speed system line	x					

Ribs

	Very Good	Good	Fair	Acceptable	Poor	Notes:
Condition	x	x				
Damage Notes	Sand removed.					

Please make sure pre-flight checks and a test inflation are carried out before flying.

Thank you,

Customer Details

Name **Brian Parkinson**

Paraglider Details

Manufacturer **Ozone**

Model **Buzz Z6**

Size **L**

Weight Range **95 -115kg**

Serial No **BZ6L.U.01L.102**

Colour(s) **Magenta,Purple,Grey,White.**

Porosity

Top Surface at Leading Edge

Left	Centre	200+	Right
------	--------	------	-------

Very Good	Good	Fair	Acceptable	Poor
-----------	------	------	------------	------

Service Notes

General Glider Condition

Very Good	Good	Fair	Acceptable	Poor
x				

Checked By: **Mike,Claire**

Date: **11/03/2024**

Under Surface

	Tape Repairs	Panel Replacements	Notes:
Previous Repairs	No		
New Repairs	No		
Stitching	Good.		

Material	Very Good	Good	Fair	Acceptable	Poor	Notes:
Fading		x				Some discolouring
Delamination		x				
Line Tabs		x				
Cleanliness		x				Few marks on T/Edge.
Cloth condition		x				

Top Surface

	Tape Repairs	Panel Replacements	Notes:
Previous Repairs	No		
New Repairs	No		
Stitching	One seam unpuckered.		

Material	Very Good	Good	Fair	Acceptable	Poor	Notes:
Fading		x				White discoloured.
Delamination		x				
Cleanliness		x	x			
Cloth condition		x				

Lines

Material	Very Good	Good	Fair	Acceptable	Poor	Notes:
A Lines		x				
B Lines		x				
C Lines		x				
D Lines		x				
Upper Brake Lines		x				

Line Strength	Actual	Minimum	Acceptable?	
Main Centre A/B			Yes	No
Mid Centre A	163	40	Yes	No
			Yes	No
			Yes	No

Replaced Lines	Left		Right	
	Upper	Main	Upper	Main
A Lines	1			
B Lines				
C Lines				
D Lines				
Brake Lines				

Line Symmetry	Checked?		Acceptable?	
	Yes	No	Yes	No
Notes:	x		x	

Line Measurement done? (FTS,NTT) Yes No

Notes: