#### **Brakes**

	Very Good	Good	Fair	Acceptable	Poor			Ν	lotes:				
Line condition	Х												
Symmetry						FTS							
Knot Adequacy		Х											
Brake Handle	Х												
Brake Fixing	Х												
Line Length	Α	ctu	al		F	TS	Line Plan		Reset?	Yes	No	)	Х
Line length Tip st.	Α	ctu	al				Line Plan		Reset?	Yes	No	)	

#### Risers

	Very Good	Good	Fair	Acceptable	Poor	Notes:
Webbing	х					
Stitching	Х					
Fading	Х					
Pulleys	Х					
Maillons	Х					
Line Tidies	Х					
Speed system line	х					

## Ribs

	Very Good	Good	air	Acceptable	Poor	Notes:
Condition	Х					
Damage Notes						

Please make sure pre-flight checks and a test inflation are carried out before flying.

Thank you,



Old Chapel Church Hill Newhaven BN9 9LN 01273 516332

# **Paraglider Service Report**

## **Customer Details**

Name Tony Sherrington

# **Paraglider Details**

Manufacturer Skywalk

Model Chili 5

Size M

Weight Range 95-115

Serial No **50MMY512243732 (Oct 23)** 

Colour(s) Green Yellow White

# **Porosity**

Top Surface at Leading Edge

Left	į			Centre	>	200	Right		
Very Good	Х	Good	į	Fair	į	Accep	table	Poor	į

#### **Service Notes**

**General Glider Condition** 

Very Good	Good	Fair	Acceptable	Poor
х				

Checked By: Ross

**Date:** 31/10/2024

	pe Repairs	Panel placements	Notes:	Material		+-	Fair	eptable	Poor		Note	s:		
		Vi .		A Lines	Х									
Previous Repairs				B Lines	х									
New Repairs				C Lines	х									
Stitching			Good	D Lines	х									
		-  -		Upper Brake Lines	Х									
Material	Fair Good Very Good	Poor	Notes:	Line Strength				Actı	ıal	Mi	nimum	Acc	eptable	e?
	٥	e		Main Centre A/B				N/	4			Yes	No	
Fading	х											Yes	No	,
Delamination	х											Yes	No	,
Line Tabs	х											Yes	No	,
Cleanliness	х									•			-	
Cloth condition	х													
				Replaced Lines				Lef	t			Right		
Top Surface						Upp	er		Ma	in	Upper		Main	
	Tape Repairs	Panel Replacements	Notes:	A Lines B Lines C Lines D Lines Brake Lines										
Previous Repairs														
New Repairs														
Stitching			Good	Line Symmetry			Cł	neck	ed?		A	ceptab	le?	
					)	/es	- 1		No		Yes		No	T
	Ve	Acc		Notes:						FTS				
Material	Fair Good Very Good	Poor ceptable	Notes:	Line Measurement of	lone? (I	FTS,	NTT	)		Yes	x No	İ		
Fading	х			Notes:										
Delamination	x													
Cleanliness	x			<b>⊣</b>										
Cloth condition	x													
	1 ** 1 1													

Lines

**Under Surface**