



Old Chapel  
Church Hill  
Newhaven  
BN99LN  
01273 516332

**Paraglider Service Report**

**Brakes**

	Very Good	Good	Fair	Acceptable	Poor	Notes:
Line condition		x				
Symmetry		x				
Knot Adequacy		x				
Brake Handle		x				
Brake Fixing		x				
Line Length	Actual	1620		Line Plan	1625	Reset? Yes No x
Line length Tip st.	Actual			Line Plan		Reset? Yes No

**Risers**

	Very Good	Good	Fair	Acceptable	Poor	Notes:
Webbing		x				
Stitching		x				
Fading		x				
Pulleys		x				
Maillons		x				
Line Tidies		x				
Speed system line		x				

**Ribs**

	Very Good	Good	Fair	Acceptable	Poor	Notes:
Condition		x				
Damage Notes						

Please make sure pre-flight checks and a test inflation are carried out before flying.

Thank you,

**Customer Details**

Name **Steve Porter**

**Paraglider Details**

Manufacturer **Advance**

Model **Sigma 10**

Size **23**

Weight Range **70-88**

Serial No **6672P71607 (Jun17)**

Colour(s) **Green Purple**

**Porosity**

Top Surface at Leading Edge

Left	122	Centre	94	Right	140
------	-----	--------	----	-------	-----

Very Good	Good	x	Fair	Acceptable	Poor
-----------	------	---	------	------------	------

**Service Notes**

General Glider Condition

Very Good	Good	Fair	Acceptable	Poor
	x			

**Checked By:** Mike, Ross

**Date:** 19/04/2021

**Under Surface**

	Tape Repairs	Panel Replacements	Notes:
Previous Repairs			
New Repairs	1		
Stitching	Good		

<b>Material</b>	Very Good	Good	Fair	Acceptable	Poor	Notes:
Fading		x				
Delamination		x				
Line Tabs	x	x				
Cleanliness	x	x				
Cloth condition	x					

**Top Surface**

	Tape Repairs	Panel Replacements	Notes:
Previous Repairs			
New Repairs			
Stitching	Good		

<b>Material</b>	Very Good	Good	Fair	Acceptable	Poor	Notes:
Fading		x				
Delamination		x				
Cleanliness		x				
Cloth condition	x					

**Lines**

<b>Material</b>	Very Good	Good	Fair	Acceptable	Poor	Notes:
<b>A Lines</b>		x				
<b>B Lines</b>		x				
<b>C Lines</b>		x				
<b>D Lines</b>						
<b>Upper Brake Lines</b>	x					

<b>Line Strength</b>	Actual	Minimum	Acceptable?	
Main Centre A/B	>170	140	Yes	x No
			Yes	No
			Yes	No
			Yes	No

<b>Replaced Lines</b>	<b>Left</b>		<b>Right</b>	
	Upper	Main	Upper	Main
<b>A Lines</b>				1
<b>B Lines</b>				
<b>C Lines</b>		1		
<b>D Lines</b>				
<b>Brake Lines</b>	1			

<b>Line Symmetry</b>	Checked?		Acceptable?	
	Yes	x No	Yes	x No
Notes:				

**Line Measurement done? (FTS,NTT)**      **Yes**      **No**      x

<b>Notes:</b>