

## Glider Service

Job Number	B19275GS	Wing Model	AIRDESIGN - UFO / 21
Hours		Serial number	UFO213P180210A
Colours	White, Purple, Green	Technician / Date	James/Cassy / 30-03-2021

### Summary

	Excellent	V. Good	Good	Fair	Tired	Failed
Overall glider condition		✓				

### Comments

### Porosity

	Excellent	V. Good	Good	Fair	Tired	Failed	Left	Center	Right
Top Surface	✓						275+	275+	275+
Bottom Surface							-	-	-

Comments Technician: James

### Fabric Strength

Result: Pass ✓

Comments Technician: James

### Riser Inspection

	Excellent	V. Good	Good	Fair	Tired	Failed	Damaged	Comments
--	-----------	---------	------	------	-------	--------	---------	----------

Webbing	✓							dyneema riser lines
---------	---	--	--	--	--	--	--	---------------------

Brake handles & keepers	✓							
-------------------------	---	--	--	--	--	--	--	--

Maillons							n/a
----------	--	--	--	--	--	--	-----

Maillons inserts / O rings							n/a
----------------------------	--	--	--	--	--	--	-----

Pulleys or rings	✓							
------------------	---	--	--	--	--	--	--	--

Speed system / trimmers	✓							
-------------------------	---	--	--	--	--	--	--	--

Comments Technician: Cassy

### Canopy Inspection

	Excellent	V. Good	Good	Fair	Tired	Failed	Damaged	Comments
--	-----------	---------	------	------	-------	--------	---------	----------

Leading edge	✓							
--------------	---	--	--	--	--	--	--	--

Cell walls	✓							
------------	---	--	--	--	--	--	--	--

Top surface	✓							
-------------	---	--	--	--	--	--	--	--

Bottom surface	✓							
----------------	---	--	--	--	--	--	--	--

Trailing edge	✓							
---------------	---	--	--	--	--	--	--	--

Stitching	✓							
-----------	---	--	--	--	--	--	--	--

Line tabs	✓							
-----------	---	--	--	--	--	--	--	--

Colour fading	✓							
---------------	---	--	--	--	--	--	--	--

Delamination	✓							
--------------	---	--	--	--	--	--	--	--

Cleanliness	✓							
-------------	---	--	--	--	--	--	--	--

Comments Technician: Cassy

### Line Inspection

	Excellent	Very Good	Good	Fair	Tired	Failed	No. replaced	Comments
--	-----------	-----------	------	------	-------	--------	--------------	----------

Main lines	✓						0	
------------	---	--	--	--	--	--	---	--

Mid and uppers	✓						0	
----------------	---	--	--	--	--	--	---	--

Brake lines	✓						0	
-------------	---	--	--	--	--	--	---	--

Comments Technician: Cassy

### Line Strength Assessment

Line type	Side	Line code	Damaged	V. Good	Good	Fair	Tired	Failed	Comments
-----------	------	-----------	---------	---------	------	------	-------	--------	----------

Comments Line condition precludes the need for testing. Technician: James

### Line Length Measurement

Comments Full measure of all overall line lengths by laser completed. See separate page for full details Technician: James