| R o I Number: | 159469. |
|---|---|
| BHPA No: | Yr: No: |

British Hang Gliding and Paragliding Association Ltd
The Old Schoolroom Loughborough Road Leicester LE4 5PJ
Tel (0116) 2611322
24 hour answering
Fax (0116) 2611323

# BHPA EMERGENCY PARACHUTE SYSTEMS: RECORD OF INSPECTION

The following equipment has been subject to a detailed routine parachute system safety inspection:

| | | | | | | |
|---|---|---|---|---|---|---|
| Harness (make, model, size) | N/A | Serial Number | | D.o.M. | | Eqpt. supplied/n.s. |
| R. Parachute (make, model, size) | BGW YETI CROSS 38 | Serial Number | 0421 | D.o.M. | 04/16 | ~~Eqpt. supplied~~/n.s. |
| Deployment Bag (make, model, size) | BGW. | Serial Number | | D.o.M. | | ~~Eqpt. supplied~~/n.s |

**OWNER'S NAME:** FLYBUBBLE **TELEPHONE NO.** _____

| | | | Y / N / NA |
|---|---|---|---|
| **DISASSEMBLY** | | | |
| 1. | Tool Count | | ✓ |
| 2. | Check deployment | | N/A |
| 3. | Steerable designs: steering toggles within reach | | N |
| 4. | Bridle routing | | N/A |
| 5. | Safety Notice check: canopy, deployment bag and harness | | N ✓ |
| 6. | Manufacturer's manual for parachute, container ~~and harness~~ | | |
| **INSPECTION** | | | **Serviceable / NOT Serviceable** |
| 7. | Deployment bag serviceability | a) grommets, bungee cord, closure loop | ✓ |
| | | b) handle, sewing reinforcement | N/A |
| | | c) locking pin(s) | N/A |
| 8. | Canopy size: (manufacturer's canopy data stamp/~~measured fabric area~~) | | 38 m2 |
| 9. | Canopy max. all up weight: (manufacturer's canopy data stamp/~~calculated~~) | | 126 kg |
| 10. | Canopy condition, material, seams and stitching | | ✓ |
| 11. | Canopy fabric strength: thumb test | | ✓ |
| 12. | Suspension lines: condition, stitching and attachment method | | ✓ |
| 13. | Bridle length (hg)/overall length (pg) | | N/A m |
| 14. | Bridle/Risers serviceability, stitching, swivels | | ✓ |
| 15. | Connectors: tightness, condition, strength | | N/A |
| 16. | Harness container: grommets, webbing, stitching and material | | N/A |
| 17. | Harness: attachment points | | N/A |
| **REASSEMBLY** | | | **Yes / No** |
| 18. | Canopy packed according to the manufacturer's manual / BHPA method, if no manual | | ✓ |
| 19. | Deployment bag: size, mouthlock tension | | ✓ |
| 20. | Canopy is acceptable fit in harness container | | |
| 21. | Pin and ring closure systems: | a) harness container closure pin(s) tension | |
| | | b) locking pins release before tension is placed on the deployment bag | |
| 22. | *Velcro closure systems:* | *a) velcro not clogged or worn* | N/A |
| | | b) deployment bag can be extracted with a single movement | |
| 23. | Check bridle routing | | |
| 24. | Deployment handle: correct side, accessible | | |
| 25. | Accidental deployment stretch check | | |
| 26. | Check parachute does not interfere with any control movement (eg pg speed bar operation) | | |
| 27. | Pull check | | |
| 28. | Tool count | | ✓ |

**Comments:**

**In the personal opinion of the Packer, the equipment at the time of examination was considered to be:** (delete as appropriate)

✓ Fit for further use
• Unfit for further use (and so has not been repacked) Owner's Signature: N/A

Whilst the equipment has been inspected with all reasonable care, the opinion expressed by the Inspector does not give or imply a guarantee that the equipment is free from defects other than those identified above.

Packed and Inspected by: M. MILLWOOD BHPA No. 729 Signature: M. Millwood

Supervision (if applicable): _____ BHPA No. _____ Signature: _____

Date: 20-04-2021.