



Glider Service

Job Number	B18210LM	Wing Model	OZONE - SPYDER / 28
Hours	14	Serial number	SD28-S-34D-049
Colours	Red, Green, Orange, White	Technician / Date	James / 01-10-2020

Summary

Overall glider condition	Excellent	V. Good	Good	Fair	Tired	Failed
--------------------------	-----------	---------	------	------	-------	--------

Comments

Porosity

	Excellent	V. Good	Good	Fair	Tired	Failed	Left	Center	Right
Top Surface	✓						-	275+	-
Bottom Surface	✓						-	275+	-

Comments

Technician: James

Line Strength Assessment

Line type	Side	Line code	Damaged	V. Good	Good	Fair	Tired	Failed	Comments
-----------	------	-----------	---------	---------	------	------	-------	--------	----------

Comments Line condition and little flying hours precludes the need for testing.

Technician: James

Line Length Measurement

Comments Full measure of all overall line lengths by laser completed. See separate page for full details

Technician: James

